

Central Plumbing & Rooter
P.O Box 2533
Alameda, CA 94501
Lic#815962

10-31-07

2224 Jefferson
Berkeley Ca.

Sewer lateral inspection shows sewer is cast iron from house outlet (rear building) up to curb. Could not locate house outlet cleanout which is required by ordinance also curbside cleanout appears to be buried and must be exposed.

We hereby submit specifications and estimate for:

Installation of house outlet cleanout includes concrete work.
Exposing curbside cleanout
Permits
Video inspection of line

Sewer will then be reinspected video will be given to realtor or homeowner for submittal to city for compliance issuance.

\$1,100.00

Thank you
Paul Croxton
510-521-1411